

**INTERNATIONAL ROAD DYNAMICS INC.**702 43<sup>rd</sup> Street East, Saskatoon SK Canada

☎ 317-694-4224

**- Site Service Report -****IRD SO.: 11167****IRD Contract No.:****From: Steve Schroeder****State: Delaware****Project Name/Location: Rt 113 Georgetown, De****Service Date(s): 2-7-11****Job Description: Perform annual site inspection.**

**Work Completed:** Drove to site. Performed visual inspection of sensors. Loop Grout is coming out of the road. I removed all solder sleeves and wired kistlers directly. Performed an electrical check. Loop shield resistance is really low. Recommend loop replacement.

**Work Remaining:** None**Parts Used:**

Part Name	Part Number	Quantity Used

**Mileage : 150 miles****Hours Worked: 3 hours****Notes:****Action Items:**

Item	Action Required	Ownership
1.		
2.		
3.		
4.		